# Wo

## Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/17017UC-0791/1

Work Order Type: Weatherization

**Audit Name:** 17017UC-0791

#### **CLIENT INFORMATION**

Client ID: 17017UC-0791

#### **AGENCY INFORMATION**

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:
Cookeville, TN 38506 Email Address:

Agency Contact: Pridgeon, Wayne Work Phone:

Cell Phone: (931) 273-9616

Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

1962 home 1652 sq ft

### **Measures**

	Measure 1 Infi	Itration Redctn			Componen	ts			Inspected
C	insulate glaze 1 install t install 5	terior and exterior of 13 version and exterior and ext	& weather		trip				
					Estimated			Actual	<b>T</b> . 4. 4
	Material / Labor Miscellaneous Supplies	Description / Comment Infiltration Reduction	<b>Units</b> Each	<b>Qty</b> 1	Unit Cost	Total	Qty	Unit Cost	Total
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 2 DW	H Tank Insulation			Componen				Inspected
C	comment		Unite		Estimated	<u>'</u>	- Ofw	Actual	
<i>C</i>		Description / Comment  DHW Tank Insulation	<i>Units</i> Each	<b>Qty</b> 1	-		Qty		Inspected Total
<i>C</i>	Comment  Material / Labor  Hot Water	Description / Comment		Qty	Estimated	<u>'</u>	Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Hot Water	Description / Comment  DHW Tank Insulation  R-10 minimum-use		Qty	Estimated	<u>'</u>	Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment	Description / Comment  DHW Tank Insulation  R-10 minimum-use bubble wrap	Each	<b>Qty</b> 1	Estimated	<u>'</u>	Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment Labor	Description / Comment  DHW Tank Insulation  R-10 minimum-use bubble wrap	Each	<b>Qty</b> 1	Estimated	<u>'</u>	Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment Labor	Description / Comment  DHW Tank Insulation  R-10 minimum-use bubble wrap	Each	<b>Qty</b> 1	Estimated	<u>'</u>	Qty	Actual	
<b>C</b> # 1	Material / Labor Hot Water Equipment Labor	Description / Comment  DHW Tank Insulation  R-10 minimum-use bubble wrap	Each	<b>Qty</b> 1	Estimated	<u>'</u>		Actual	

		/H Pipe Insulation			Componer	nts			Inspected
C	Comment 10 ft				Estimated	4		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Insulation	DHW Pipe Insulation	Each	1					1014
•	modiation	wrap water pipes							
2	Labor	DHW Pipe Insulation	Each	1					
(	Other Detail						<b>-</b>		
				Measur	e Sub Total:			Sub Total:	
	Measure 4 Flo Comment	or Ins. R-19			Componer			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1652					
(	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 5 Sto	rm Windows			Componen	ts B3,C5			Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
3 Other	Storm Window	Each Window	4					
	<99 U.I ea Over 100 UI							
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	ndow Replacement			Componen				Inspected
Measure 6 Wir	DW .	Unito		Componen Estimated	<u>'</u>	Oftv	Actual	
Measure 6 Wir Comment 1 windo # Material / Labor	Description / Comment	<b>Units</b> SaFt	Qty	Componen		Qty		Inspected Total
Measure 6 Wir Comment 1 windo # Material / Labor 1 Windows	DW .	<i>Units</i> SqFt		Componen Estimated	<u>'</u>	Qty	Actual	
Measure 6 Wir Comment 1 windo	Description / Comment		Qty	Componen Estimated	<u>'</u>	Qty	Actual	
Measure 6 Wir Comment 1 windo # Material / Labor 1 Windows	Description / Comment		Qty	Componen Estimated	<u>'</u>	Qty	Actual	
Measure 6 Wir Comment 1 windo # Material / Labor 1 Windows	Description / Comment		<b>Qty</b> 3.833	Componen Estimated	<u>'</u>		Actual	

Measure 7 CO Monitor is Needed				Componen	1	Inspected			
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	9-volt CO Monitor	Each	1					
2	Labor	Labor	Hour	1					
(	Other Detail						,		
				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	